

Aircraft Status Report

Townsend Aviation

N5X5X5

LR31

Page 1 of 1

May 16, 2006

Pending Maintenance

Type	Description	Item ID/Part No	ATA Code	Hrs Rem	Cyc Rem	Days Rem	Mos Rem
Overhaul	O/H Co-pilots O2 Mask	MC10-15-01 s/n47366	35-10				<u>0</u>
Inspect	Weigh Aircraft		08-10				<u>0</u>
Inspect	B2620005 #1 Eng. Fire Ext. CHK		26-20				<u>0</u>
Inspect	B2620005 #2 Eng. Fire Ext.CHK		26-20				<u>0</u>
Inspect	H2750044 L/H Flap Cam Brg Insp		27-50	<u>0.0</u>			
Inspect	A/C system pressure switch CHK		21-00	<u>0.0</u>			
Inspect	A/C Comp Blades Check HOBBS		21-00	<u>0.0</u>			
Inspect	K3414000Radio Alt. Ant/Bond CK	Radio Alt.Check	34-10				<u>0</u>
Inspect	L5710035Inspct Wing I/B DryBay	Dry Bay	57-10				<u>0</u>
Inspect	30 Day fire bottle Insp.		26-00				<u>0</u>
Inspect	PS835/855 Emer.Power Supply CK	PRIMARY	05-20				<u>1</u>
Inspect	PS835/855 Emer.Power Supply CK	SECONDARY	05-20				<u>1</u>
Inspect	Batt. Installation Insp.		05-20				<u>1</u>
Inspect	#1 Xponder 91.413 check	066-1103-00 s/n4004	34-00				<u>1</u>
Inspect	#2 Xponder 91.413 check	066-1103-00 s/n 4112	34-00				<u>1</u>
Inspect	Check Pilots Altimeter 91.411	Pilots Alttimeter	34-10				<u>1</u>
Inspect	Chk Co-Pilots Altimeter 91.411	Pilots Alttimeter	34-10				<u>1</u>
Inspect	Chk. Std-By Altimeter 91.411	p/n N834-9001	34-10				<u>1</u>
Inspect	#1 Air Data Computer 91.411	p/n 065-0082-03	34-10				<u>1</u>
Inspect	#2 Air Data Computer 91.411	p/n 065-0082-03	34-10				<u>1</u>
Inspect	Perform Static Leak Check	Leak Check Static	34-10				<u>1</u>
Replace	NLG Actuator Extend Hose	23070006-83	32-30	<u>6.3</u>			11
Inspect	Left 300 Hour Eng. Insp.		71-00	<u>17.5</u>			
Inspect	Left 150 Hour Eng. Insp.		71-00	<u>21.6</u>			

Unresolved Squawks

Squawk #	Reported	Description of Problem	MEL	W/C Status
1023-1	07/15/2004 Hrs: 3,753	Slight fluctuation of L/H oil PSI	MEL Cat: - Due Date: Due Hrs:	Pending